

### Commonwealth of Massachusetts

## **Title 5 Official Inspection Form**

Subsurface Sewage Disposal System Form - Not for Voluntary Assessments

6 Berkley Circle		*			
Property Address					
Mary Griffin					
Owner's Name		-			
Hingham		M.A.	02043	June 1, 2021	
City/Town		State	Zip Code	Date of Inspection	

Inspection results must be submitted on this form. Inspection forms may not be altered in any way. Please see completeness checklist at the end of the form.

Important: When filling out forms on the computer, use only the tab key to move your cursor - do not use the return key.





A.	General Information		
1.	Inspector:		
	Paul J Foisy		
	Name of Inspector		
	E.L. Margetts & Sons Inc		
	Company Name		
	Off 97 Ward Street		
	Company Address		
	Hingham	M.A. 02043	
	City/Town	State Zip Code	
	781-749-0559	SI4517	
	Telephone Number	License Number	

### **B.** Certification

I certify that I have personally inspected the sewage disposal system at this address and that the information reported below is true, accurate and complete as of the time of the inspection. The inspection was performed based on my training and experience in the proper function and maintenance of on site sewage disposal systems. I am a DEP approved system inspector pursuant to Section 15.340 of Title 5 (310 CMR 15.000). The system:

□ Passes	☐ Conditionally Passes	] Fails
☐ Needs Further Evaluation by	y the Local Approving Authority	
Inspector's Signature	Jun 1, 20	231
The evictors increases a hell author	Date	A

The system inspector shall submit a copy of this inspection report to the Approving Authority (Board of Health or DEP) within 30 days of completing this inspection. If the system is a shared system or has a design flow of 10,000 gpd or greater, the inspector and the system owner shall submit the report to the appropriate regional office of the DEP. The original should be sent to the system owner and copies sent to the buyer, if applicable, and the approving authority.

\*\*\*\*This report only describes conditions at the time of inspection and under the conditions of use at that time. This inspection does not address how the system will perform in the future under the same or different conditions of use.



## **Commonwealth of Massachusetts**

	erkley Circle perty Address				
	ry Griffin				
	ner's Name	·			
	gham		M.A.	02043	June 1, 2021
City	/Town		State	Zip Code	Date of Inspection
3.	Certification (c	ont.)			
	Inspection Summary:	Check A,B,C,D or	E / always	complete all of	Section D
۹)	System Passes:				
					failure criteria described eria not evaluated are
	Comments:				
		7. 1500 GAL TANK			EDROOMS, SOIL LOGS BY FIELD. RECOMMEND
			-		
3)	System Conditionall	y Passes:			
3)	☐ One or more syste	em components as ed. The system, up			nal Pass" section need to be cement or repair, as approved by
3)	One or more system replaced or repair the Board of Heal	em components as ed. The system, up th, will pass. s", "no" or "not dete	oon completi	on of the repla	
3)	One or more system replaced or repair the Board of Heal Check the box for "yedetermined," please et a common the septic tank is met unsound, exhibits sub	em components as ed. The system, up th, will pass. s", "no" or "not dete xplain. al and over 20 yea stantial infiltration o	ermined" (Y, rs old* <b>or</b> th or exfiltration	on of the repla  N, ND) for the e septic tank (volume tank failure	cement or repair, as approved by
3)	One or more systereplaced or repair the Board of Heal Check the box for "yed determined," please et ank is met unsound, exhibits sub inspection if the existing Health.	em components as ed. The system, up th, will pass.  s", "no" or "not detexplain.  al and over 20 yea stantial infiltration on the texplaced will pass inspection	ermined" (Y,  rs old* <b>or</b> th  or exfiltration  with a comp	N, ND) for the e septic tank (volume tank failure blying septic tank urally sound, n	cement or repair, as approved by following statements. If "not whether metal or not) is structural is imminent. System will pass hk as approved by the Board of ot leaking and if a Certificate of
3)	One or more systereplaced or repair the Board of Heal Check the box for "yed determined," please et ansound, exhibits subinspection if the existing Health.	em components as ed. The system, up th, will pass.  s", "no" or "not detexplain.  al and over 20 yea stantial infiltration on the texplaced will pass inspection	ermined" (Y, rs old* <b>or</b> th or exfiltration with a comp if it is struct ss than 20 ye	N, ND) for the e septic tank (vertically sound, nears old is available.	cement or repair, as approved by following statements. If "not whether metal or not) is structural is imminent. System will pass hk as approved by the Board of ot leaking and if a Certificate of
3)	One or more systereplaced or repair the Board of Heal Check the box for "yed determined," please et ansound, exhibits subinspection if the existing Health.  * A metal septic tank is Compliance indicating	em components as ed. The system, up th, will pass.  s", "no" or "not detexplain.  al and over 20 year stantial infiltration or the tended will pass inspection that the tank is lest	ermined" (Y, rs old* <b>or</b> th or exfiltration with a comp if it is struct ss than 20 ye	N, ND) for the e septic tank (vertically sound, nears old is available.	cement or repair, as approved by following statements. If "not whether metal or not) is structural is imminent. System will pass hk as approved by the Board of ot leaking and if a Certificate of
3)	One or more systereplaced or repair the Board of Heal Check the box for "yed determined," please et ansound, exhibits subinspection if the existing Health.  * A metal septic tank is Compliance indicating	em components as ed. The system, up th, will pass.  s", "no" or "not detexplain.  al and over 20 year stantial infiltration or the tended will pass inspection that the tank is lest	ermined" (Y, rs old* <b>or</b> th or exfiltration with a comp if it is struct ss than 20 ye	N, ND) for the e septic tank (vertically sound, nears old is available.	cement or repair, as approved by following statements. If "not whether metal or not) is structural is imminent. System will pass hk as approved by the Board of ot leaking and if a Certificate of
3)	One or more systereplaced or repair the Board of Heal Check the box for "yed determined," please et ansound, exhibits subinspection if the existing Health.  * A metal septic tank is Compliance indicating	em components as ed. The system, up th, will pass.  s", "no" or "not detexplain.  al and over 20 year stantial infiltration or the tended will pass inspection that the tank is lest	ermined" (Y, rs old* <b>or</b> th or exfiltration with a comp if it is struct ss than 20 ye	N, ND) for the e septic tank (vertically sound, nears old is available.	cement or repair, as approved by following statements. If "not whether metal or not) is structural is imminent. System will pass hk as approved by the Board of ot leaking and if a Certificate of
3)	One or more systereplaced or repair the Board of Heal Check the box for "yed determined," please et ansound, exhibits subinspection if the existing Health.  * A metal septic tank is Compliance indicating	em components as ed. The system, up th, will pass.  s", "no" or "not detexplain.  al and over 20 year stantial infiltration or the tended will pass inspection that the tank is lest	ermined" (Y, rs old* <b>or</b> th or exfiltration with a comp if it is struct ss than 20 ye	N, ND) for the e septic tank (vertically sound, nears old is available.	cement or repair, as approved by following statements. If "not whether metal or not) is structural is imminent. System will pass hk as approved by the Board of ot leaking and if a Certificate of

### **Commonwealth of Massachusetts**

		ey Circle Address	9					<u> </u>
Ма	ry G	riffin						
Owi	ner's	Name						
	gha			M.A.	020		June 1, 2021	
	/Tow			State	Zip C	ode	Date of Inspection	on
В.	Ce		ation (cont.)					
			Chamber pumps/alarms not o /alarms are repaired.	perational.	System	will pass	s with Board of H	ealth approval if
	B)	Syster	n Conditionally Passes (con	t.):				
		to brok	vation of sewage backup or br en or obstructed pipe(s) or du spection if (with approval of B	e to a brok	en, settle	ic water ed or un	level in the distri even distribution	bution box due box. System will
			broken pipe(s) are replaced		□ Y	□ N	☐ ND (Explain	n below):
			obstruction is removed		□ Y	□ N	☐ ND (Explain	n below):
			distribution box is leveled or	replaced	□ Y	□N	☐ ND (Explain	n below):
				:				
			•					
		· · · · · · · · · · · · · · · · · · ·					. •	
			stem required pumping more will pass inspection if (with a					cted pipe(s). The
		□ ·	broken pipe(s) are replaced		☐ Y	□N	☐ ND (Explain	n below):
			obstruction is removed		☐ Y	□ N	☐ ND (Explain	n below):
							· · · · · · · · · · · · · · · · · · ·	
	-	107-00-00-00-00-00-00-00-00-00-00-00-00-0						
	C)	Furthe	r Evaluation is Required by	the Board	of Heal	th:		
		Conditi the sys	ons exist which require furthe tem is failing to protect public	r evaluatior health, saf	by the lety or the	Board of e enviro	f Health in order nment.	to determine if
		15.303	tem will pass unless Board (1)(b) that the system is not and the environment:					
			Cesspool or privy is within 50	) feet of a s	surface w	vater		
			Cesspool or privy is within 50	) feet of a b	ordering	y vegeta	ted wetland or a	salt marsh

## **Commonwealth of Massachusetts**

# Title 5 Official Inspection Form Subsurface Sewage Disposal System Form - Not for Voluntary Assessments

	Berkley Circ						
	peny Address ry Griffin	5					
	ner's Name						
Hir	gham			M.A.	02043	June 1, 2021	
	/Town			State	Zip Code	Date of Inspection	
B.	Certifi	cation	(cont.)				
	2. Sy deter safet  T 100 for suppl T suppl T suppl T more	ystem wi ymines the y and end he system y well. system ha from a p	ill fail unless the Bo hat the system is fun nvironment: m has a septic tank a surface water supply of m has a septic tank a m has a septic tank a	nctioning in a and soil absorp or tributary to and SAS and t and SAS and t SAS and the S vell**.	a manner that otion system (S a surface wate ne SAS is with	Vater Supplier, if any) protects the public health,  SAS) and the SAS is within or supply. In a Zone 1 of a public water In 50 feet of a private water In 100 feet but 50 feet or	
	coliform b	eacteria in than 5 p ed to this	ndicates absent and t pm, provided that no	the presence	of ammonia nit	P certified laboratory, for fecal rogen and nitrate nitrogen is equal pered. A copy of the analysis must	
				· · · · · · · · · · · · · · · · · · ·			
	-				409		
D)	System F	ailure C	riteria Applicable to	All Systems	: :		
	You <u>must</u> indicate "Yes" or "No" to each of the following for <u>all</u> inspections:						
	Yes	No					
		$\boxtimes$	Backup of sewage clogged SAS or c		r system comp	oonent due to overloaded or	
		$\boxtimes$		ding of effluen	t to the surface	e of the ground or surface waters	
		$\boxtimes$		in the distribut		outlet invert due to an overloaded	
					than 6" below	invert or available volume is less	

### **Commonwealth of Massachusetts**

## Title 5 Official Inspection Form

Subsurface Sewage Disposal System Form - Not for Voluntary Assessments

6 B	Berkley Circ	:le				
	perty Address					
	ry Griffin				· · · · · · · · · · · · · · · · · · ·	
	ner's Name			N4 A	02043	June 1, 2021
	ngham r/Town			M.A State	Zip Code	Date of Inspection
	Certific	cation	(cont.)		· · · · · · · · · · · · · · · · · · ·	
	Yes	No				
		$\boxtimes$	Required pumping obstructed pipe(s)			st year <i>NOT</i> due to clogged or 
		$\boxtimes$	Any portion of the	SAS, cesspo	ol or privy is be	elow high ground water elevation.
			Any portion of ces tributary to a surfa			feet of a surface water supply or
		$\boxtimes$	Any portion of a ce	esspool or pri	vy is within a Z	one 1 of a public well.
			Any portion of a co	esspool or pri	vy is within 50	feet of a private water supply wel
			from a private wat system passes if laboratory, for fe of ammonia nitro	er supply wel the well wat cal coliform gen and nitr other failure	l with no accepter analysis, p bacteria indic rate nitrogen is criteria are tr	100 feet but greater than 50 feet btable water quality analysis. [This erformed at a DEP certified ates absent and the presence s equal to or less than 5 ppm, riggered. A copy of the analysis this form.]
			The system is a ce	esspool servi	ng a facility wit	h a design flow of 2000gpd-
			criteria exist as de	scribed in 31 uld contact th	0 CMR 15.303 ne Board of He	or more of the above failure , therefore the system fails. The alth to determine what will be
E)			o be considered a l 000 gpd to 15,000 g		the system n	nust serve a facility with a
	For large a			her "yes" or "	no" to each of	the following, in addition to the
	Yes	No				
			the system is withi	n 400 feet of	a surface drink	king water supply
			the system is withi	n 200 feet of	a tributary to a	surface drinking water supply
			the system is local Area – IWPA) or a			rea (Interim Wellhead Protection water supply well

If you have answered "yes" to any question in Section E the system is considered a significant threat, or answered "yes" in Section D above the large system has failed. The owner or operator of any large system considered a significant threat under Section E or failed under Section D shall upgrade the system in accordance with 310 CMR 15.304. The system owner should contact the appropriate regional office of the Department.

## **Commonwealth of Massachusetts**

## Title 5 Official Inspection Form Subsurface Sewage Disposal System Form - Not for Voluntary Assessments

rop'	erty Addre	ss			$\star = - \epsilon^* \cdot \cdot \cdot$				
	ry Griffin								
-	er's Name				00040	1 0001			
	gham			M.A.	02043	June 1, 2021  Date of Inspection			
	Town			State	Zip Code	Date of Inspection			
<b>C</b> .	Chec	klist							
	Check if	the follo	wing have been done. \	ou <b>must</b> inc	licate "yes" or '	'no" as to each of the following:			
	Yes	No							
	$\boxtimes$		Pumping information	n was provid	ed by the owne	er, occupant, or Board of Health			
			Were any of the sys	tem compon	ents pumped o	out in the previous two weeks?			
	$\boxtimes$		Has the system rec	eived normal	flows in the pr	revious two week period?			
		$\boxtimes$	this inspection?			o the system recently or as part of			
			Were as built plans available note as N		n obtained and	examined? (If they were not			
			Was the facility or d	welling inspe	ected for signs	of sewage back up?			
	$\boxtimes$		Was the site inspec	ted for signs	of break out?				
	$\boxtimes$		Were all system cor	nponents, ex	cluding the SA	AS, located on site?			
			inspected for the co	Were the septic tank manholes uncovered, opened, and the interior of the tank inspected for the condition of the baffles or tees, material of construction, dimensions, depth of liquid, depth of sludge and depth of scum?					
			Was the facility owner (and occupants if different from owner) provided with information on the proper maintenance of subsurface sewage disposal systems? The size and location of the Soil Absorption System (SAS) on the site has been determined based on:						
			Existing information	. For exampl	e, a plan at the	e Board of Health.			
			Determined in the fi approximation of dis			eria related to Part C is at issue 0 CMR 15.302(5)]			
D.	Syste	m Info	ormation						
	Resider	ntial Flov	v Conditions:						
			oms (design): $\frac{4}{}$		Number of bed	drooms (actual):			

DESIGN flow based on 310 CMR 15.203 (for example: 110 gpd x # of bedrooms):

440

## **Commonwealth of Massachusetts**

	erkley Circle perty Address		· · · · · · · · · · · · · · · · · · ·		
	ry Griffin				
Owi	ner's Name				
	gham	M.A. State	02043 Zip Code	June 1, 202  Date of Inspec	
	/Town	State	Zip Code	Date of Hisper	MOII
D.	System Information				
	Description:				
					2
	Number of current residents:				-
	Does residence have a garbage grinder?				⊠ Yes □ No
	Is laundry on a separate sewage system? information in this report.)	(Include lau	ındry systen	ninspection	☐ Yes ⊠ No
	Laundry system inspected?				☐ Yes ⊠ No
	Seasonal use?				☐ Yes ⊠ No
	Water meter readings, if available (last 2 y	ears usage	(gpd)):		N.A.
	Detail:		<b>(3.</b> //		
	Sump pump?				⊠ Yes □ No
	Last date of occupancy:				CURRENTLY Date
	Commercial/Industrial Flow Conditions:				
	Type of Establishment:			· · · · · · · · · · · · · · · · · · ·	
	Design flow (based on 310 CMR 15.203):		Gallor	ns per day (gpd)	
	Basis of design flow (seats/persons/sq.ft., e	etc.):			
	Grease trap present?				☐ Yes ☐ No
	Industrial waste holding tank present?				☐ Yes ☐ No
	Non-sanitary waste discharged to the Title	5 system?			☐ Yes ☐ No
	Water meter readings, if available:		·		
	<b>9</b> /				



## **Commonwealth of Massachusetts**

erty Address							
ry Griffin ner's Name							
Hingham		M.A.	02043	June 1, 2021			
Town		State	Zip Code	Date of Inspection			
System	Information (cont.)						
Last date of	occupancy/use:		Date				
Other (desc	cribe below):						
	Gen	eral Infor	mation				
Pumping R	ecords:						
Source of ir	nformation:	<u>E.L. I</u>	E.L. MARGETTS & SONS INC				
Was systen	n pumped as part of the inspec	tion?		⊠ Yes □ No			
If yes, volur	ne pumped:	-	gallons				
How was qu	uantity pumped determined?	SITE	PROPRTY TRANSFER				
Reason for	pumping:	PRO					
Type of Sy	stem:						
	Septic tank, distribution bo	ox, soil abs	orption system				
	Single cesspool						
	Overflow cesspool						
	Privy						
	Shared system (yes or no	) (if yes, at	tach previous i	nspection records, if any)			
Innovative/Alternative technomaintenance contract (to be inspection of the I/A system			d from system	owner) and a copy of latest			
	Tight tank. Attach a copy	of the DEP	approval.				

### **Commonwealth of Massachusetts**

City/Town	State	Zip Code	Date of Inspection	
Hingham	M.A.	02043	June 1, 2021	
Owner's Name				
Mary Griffin				
Property Address				
6 Berkley Circle				

System Information (cont.)		
Approximate age of all components, date installed (if known) a SYSTEM INSTALLED 1977, ON FILE AT BOARD OF HEALT 2021		
Were sewage odors detected when arriving at the site?	E	] Yes ⊠ No
Building Sewer (locate on site plan):		
Depth below grade:	20" INCHES feet	
Material of construction:		
☐ cast iron ☐ 40 PVC ☐ other (explain):		
Distance from private water supply well or suction line:	feet	
Comments (on condition of joints, venting, evidence of leakage NO EVIDENCE OF LEAKAGE OR VENTING PROBLEMS,	e, etc.):	
Septic Tank (locate on site plan):  Depth below grade:	12" INCHES	
Material of construction:		
□ concrete    □ metal    □ fiberglass    □  1500 GAL TANK AND FILTER	polyethylene	☐ other (explain)
If tank is metal, list age:	years	
Is age confirmed by a Certificate of Compliance? (attach a cop		☐ Yes ☐ No
Dimensions:	10L X 5D X 5	W
Sludge depth:	6" INCHES	

## **Commonwealth of Massachusetts**

6 Berkley Circle

HID	er's Name		<b>A.</b> A	02042	luna 4 O	004
	gham Town		<del>M</del> .A State	02043 Zip Code	June 1, 2  Date of Insi	
	System Informatio	n (cont.)				
	Septic Tank (cont.)					
	Distance from top of sludge	to bottom o	f outlet tee or b	affle	30" INCHES	
	Scum thickness				4" INCHES	
	Distance from top of scum t	o top of outl	et tee or baffle		6" INCHES	
	Distance from bottom of scu	ım to botton	of outlet tee o	r baffle	10" INCHES	
	How were dimensions deter	rmined?			ON SITE MEA	ASUREMENTS
	INLET T. OUTLET T FILTE IS CAST IRON. DURING IN AND GREASE IN LINE. LIN	ISPECTION	LINE WAS CL	EANED O		
	Grease Trap (locate on site	plan):				
	Grease Trap (locate on site Depth below grade:	plan):			feet	
		plan):			feet	
	Depth below grade:		☐ fiberglas	s 🗆	feet polyethylene	☐ other (explain):
	Depth below grade:  Material of construction:  concrete me		☐ fiberglas	s 🗆		☐ other (explain):
	Depth below grade:  Material of construction:		☐ fiberglas	s 🗆		☐ other (explain):
	Depth below grade:  Material of construction:  concrete me  Dimensions:	tal		s 🗆		☐ other (explain):
	Depth below grade:  Material of construction:  concrete me  Dimensions:  Scum thickness	tal o top of outle	et tee or baffle			other (explain):

### **Commonwealth of Massachusetts**

Serkley Circle Derty Address						
ry Griffin						- '
ner's Name gham		M.A.	02043	June 1, 2	<b>021</b>	
/Town		State	Zip Code	Date of Insp		
System Information (cont.)		)				
Comments (on pump liquid levels as relate				fle condition	n, structu	ral integri
	<u>'</u>					
Tight or Holding Ta	nk (tank must be	pumped at tim	e of inspection)	(locate on s	ite plan):	
Depth below grade:			·	· · · · · · · · · · · · · · · · · · ·		
Material of construct	ion:					
☐ concrete ☐ metal ☐ fiberglass ☐ polyethylen					oth	er (explai
Dimensions:						
Capacity:			gallons			
Design Flow:			gallons per day			
Alarm present:			☐ Yes ☐	No		
Alarm level:		· · · · · · · · · · · · · · · · · · ·	Alarm in working	order:	Yes	☐ No
Date of last pumping	:		Date	<del></del>		
	of alarm and flo	at switches etc	.):			
Comments (condition	i di alami and no	at switchies, etc				
Comments (condition	i oi alaitti attu iloa	at switches, cit				
Comments (condition	TOT AIATH AND NO	at switches, etc				
Comments (condition	TOT alaitit and no	at switches, etc				
Comments (condition	TOT alaitit and no	at switches, etc				

## **Commonwealth of Massachusetts**

Pump Chamber (locate on site plan):  Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps an object of plan):  Pumps or alarms are not in working order, system is a conditiona Soil Absorption System (SAS) (locate on site plan, excavation not if SAS not located, explain why:	
er's Name gham Town State  M.A. D2043 Zip Code  System Information (cont.)  Distribution Box (if present must be opened) (locate on site plan): Depth of liquid level above outlet invert  Comments (note if box is level and distribution to outlets equal, any evidence of leakage into or out of box, etc.): BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE OF BOX. COVER DOWN 10 INCHES. SOME SCALLING ON SIDE WAS AT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEY  Pump Chamber (locate on site plan):  Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the plan):  * If pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not site plan and excavation not s	
Town State D2043 Town State Zip Code  System Information (cont.)  Distribution Box (if present must be opened) (locate on site plan):  Depth of liquid level above outlet invert  Comments (note if box is level and distribution to outlets equal, any evidence of leakage into or out of box, etc.):  BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE OF BOX. COVER DOWN 10 INCHES SOME SCALLING ON SIDE WAAT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEY  Pump Chamber (locate on site plan):  Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the plan):  * If pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not site plan plan plan plan plan plan plan plan	
System Information (cont.)  Distribution Box (if present must be opened) (locate on site plan):  Depth of liquid level above outlet invert  Comments (note if box is level and distribution to outlets equal, any evidence of leakage into or out of box, etc.): BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE (BOX. COVER DOWN 10 INCHES.SOME SCALLING ON SIDE WAAT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEY  Pump Chamber (locate on site plan):  Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the plan):  * If pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not site plan and excavation	June 1, 2021
Distribution Box (if present must be opened) (locate on site plan):  Depth of liquid level above outlet invert  Comments (note if box is level and distribution to outlets equal, any evidence of leakage into or out of box, etc.):  BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE (BOX. COVER DOWN 10 INCHES.SOME SCALLING ON SIDE WAAT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEV  Pump Chamber (locate on site plan):  Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the plan):  * If pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not site plan and excavation not	Date of Inspection
Distribution Box (if present must be opened) (locate on site plan):  Depth of liquid level above outlet invert  Comments (note if box is level and distribution to outlets equal, any evidence of leakage into or out of box, etc.):  BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE of BOX. COVER DOWN 10 INCHES.SOME SCALLING ON SIDE WAAT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEV  Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the plan):  * If pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not site plan and excavation not si	
Depth of liquid level above outlet invert  Comments (note if box is level and distribution to outlets equal, any evidence of leakage into or out of box, etc.): BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE (BOX. COVER DOWN 10 INCHES.SOME SCALLING ON SIDE WAAT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEY  Pumps in working order: Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation noted that is a condition of pump.)	
Depth of liquid level above outlet invert  Comments (note if box is level and distribution to outlets equal, any evidence of leakage into or out of box, etc.): BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE (BOX. COVER DOWN 10 INCHES.SOME SCALLING ON SIDE WAAT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEY  Pumps in working order: Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation noted that is a condition of pump.)	
Comments (note if box is level and distribution to outlets equal, any evidence of leakage into or out of box, etc.):  BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE (BOX. COVER DOWN 10 INCHES.SOME SCALLING ON SIDE WAAT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEV  Pump Chamber (locate on site plan):  Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not site plan not s	
evidence of leakage into or out of box, etc.): BOX WAS LEVEL WITH EQUAL DISTRIBUTION. NO EVIDENCE (BOX. COVER DOWN 10 INCHES.SOME SCALLING ON SIDE WAAT TIME OF INSPECTION.BOX LOCATED JUST OFF OF DRIVEV  Pump Chamber (locate on site plan): Pumps in working order: Alarms in working order: Comments (note condition of pump chamber, condition of pumps and the plan):  * If pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not site plan no	
Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the state of the st	OF LEAKAGE INTO OR OUT O LLLS BUT STILL WATER TIGHT
Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the state of the st	
Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the state of the st	
Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the state of the st	
Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the state of the st	
Pumps in working order:  Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and the state of the st	
Alarms in working order:  Comments (note condition of pump chamber, condition of pumps and * If pumps or alarms are not in working order, system is a conditional * Soil Absorption System (SAS) (locate on site plan, excavation not	
* If pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not	☐ Yes ☐ No*
* If pumps or alarms are not in working order, system is a conditional Soil Absorption System (SAS) (locate on site plan, excavation not	☐ Yes ☐ No*
Soil Absorption System (SAS) (locate on site plan, excavation not	nd appurtenances, etc.):
Soil Absorption System (SAS) (locate on site plan, excavation not	
Soil Absorption System (SAS) (locate on site plan, excavation not	
Soil Absorption System (SAS) (locate on site plan, excavation not	
Soil Absorption System (SAS) (locate on site plan, excavation not	
Soil Absorption System (SAS) (locate on site plan, excavation not	
Soil Absorption System (SAS) (locate on site plan, excavation not	-1
	ai pass.
If SAS not located, explain why:	t required):
ii SAS not located, explain why.	

## **Commonwealth of Massachusetts**

6 Berkley Circle

Property Address					
Mary Griffin					
Owner's Name Hingham		M.A.	02043	June 1, 20	21
City/Town		State	Zip Code	Date of Inspe	
D. System	Information (cont.)				
Type:					
	leaching pits		number:		
	leaching chambers		number:		
	leaching galleries		number:		
	leaching trenches		number, I	ength:	
$\boxtimes$	leaching fields		number, o	dimensions:	40 X 20
	overflow cesspool		number:		
	innovative/alternative sys	tem			
	Type/name of technology		-		
WAS DRY					
	s (cesspool must be pumped and configuration	as part of ins	pection) (locate	e on site plan):	
Depth – to	p of liquid to inlet invert				
Depth of se	olids layer				
Depth of se	cum layer				
Dimension	s of cesspool				
Materials o	of construction				
Indication	of groundwater inflow			☐ Yes	□ No



D

## **Commonwealth of Massachusetts**


6 Berkley Circle			
Property Address			
Mary Griffin	<u> </u>		
Owner's Name			
Hingham	M.A	02043	June 1, 2021
City/Town	State	Zip Code	Date of Inspection
D. System Information (cont.)			
Comments (note condition of soil, sign etc.):	ns of hydraulic	failure, level of	ponding, condition of vegetation
Privy (locate on site plan):			
Materials of construction:	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	
Dimensions	· ————————————————————————————————————	· · · · · · · · · · · · · · · · · · ·	
Depth of solids			
Comments (note condition of soil, sign etc.):	s of hydraulic	failure, level of	ponding, condition of vegetation

### **Commonwealth of Massachusetts**

6 Berkley Circle Property Address			
Mary Griffin Dwner's Name			
Hingham	M.A.	02043	June 1, 2021
ity/Town	State	Zip Code	Date of Inspection
D. System Information (cont.)			
Sketch Of Sewage Disposal System: I at least two permanent reference land where public water supply enters the bases.	marks or benc	hmarks. Locate	e all wells within 100 feet. Loca
<ul><li>☐ hand-sketch in the area below</li><li>☐ drawing attached separately</li></ul>			

## E. L. MARGETTS & SONS, INC.

Septic System Service Since 1912\*Four Generations
Off 97 Ward Street, Hingham, MA 02043
TEL:(781)749.0559, FAX (781)740.5049
info@elmargetts.biz



## **Commonwealth of Massachusetts**

# Title 5 Official Inspection Form Subsurface Sewage Disposal System Form - Not for Voluntary Assessments

6 Berkley Circle           Property Address           Mary Griffin           Owner's Name           Hingham         M.A.         02043         June 1, 2021           City/Town         State         Zip Code         Date of Inspection					
Property Address  Mary Griffin  Owner's Name  Hingham  M.A. 02043 June 1, 2021	City/Town	State	Zip Code	Date of Inspection	
Property Address  Mary Griffin  Owner's Name	Hingham				
Property Address	Owner's Name				
	Mary Griffin				
	Property Address				

### **D. System Information** (cont.)

Site	Exam:		
$\boxtimes$	Check S	Slope	
$\boxtimes$	Surface	e water	
$\boxtimes$	Check o	cellar	
	Shallow	w wells	
Est	imated d	donth to high ground water:	4+ feet
Ple	ase indic	icate all methods used to determine the high groun	d water elevation:
		Obtained from system design plans on record	
		If checked, date of design plan reviewed:	ite
		Observed site (abutting property/observation hole	e within 150 feet of SAS)
		Checked with local Board of Health - explain:	
		Checked with local excavators, installers - (attack	n documentation)
		Accessed USGS database - explain:	
		describe how you established the high ground wat	
	· -		

Before filing this Inspection Report, please see Report Completeness Checklist on next page.

## McS

McSweeney Associates, Inc.

Thomas F. McSweeney 1894-1977 Brian McSweeney 1923-2015 Terence K. McSweeney Colin T. McSweeney 745 Winter Street Hanson, MA 02341 (781) 826-4571 (781) 570-9381

June 3, 2021

E.L. Margetts & Sons, Inc. Off Ward Street Hingham, MA 02043

RE: 6 Berkley Circle Hingham, MA

Dear Sirs,

I completed a soil analysis at the referenced property on May 27, 2021 using the procedures described at 310 CMR 15,00 et. seq., commonly known as "Title V" of the State Environmental Code. This inspection was completed in order to determine the elevation of historical high groundwater at the site, relative to the on-site wastewater disposal system. My evaluation was conducted utilizing a test hole installed adjacent to, and 36" higher in surface elevation than, the on-site disposal system.

In the fall of 1997, I was approved by the Massachusetts Department of Environmental Protection (MaDEP) as a Soils Evaluator; my evaluation in the referenced matter was conducted in accordance with the training, experience, and expertise described at 310 CMR 15.018(2). Summarized below are the results of my analysis; as indicated, no evidence for the presence of a watertable was encountered in the test hole through the total depth of 44" below surface grade.

### **RESULTS OF SOILS ANALYSIS**

6 Berkley Circle, Hingham, Massachusetts

Depth (inche	es) Horizon	Soil Texture	Soil Color	Mottle/Other
0-16	A	Loamy Sand	10YR 3/2	None
16-32	В	Loamy Sand	10YR 5/8	None
32-44	C	Medium Sand	2.5Y 5/3	Groundwater @39"

According to the information you have provided to me, the current soil absorption system in operation at the site is a tank-distribution box- stone and pipe leaching field combination, the bottom of which is located 64" below surface grade.

As the bottom of the existing waste water disposal system is approximately 11" higher in elevation than the groundwater observed in the test hole described above, this waste water disposal system is not located within the groundwater at the site as determined by the Title V methodology.

Please feel free to contact me if I may be of any further assistance in this matter.

Sincerely,

McSweeney Associates, Inc.

Terence McSweeney, R.S.

President

Massachusetts Approved Soil Evaluator (#SE1594)

Jerene My weenen



### **Commonwealth of Massachusetts**

## **Title 5 Official Inspection Form**

Subsurface Sewage Disposal System Form - Not for Voluntary Assessments

City/Town	State	Zip Code	Date of Inspection	
Hingham	M.A.	02043	June 1, 2021	
Owner's Name				
Mary Griffin				
Property Address				
6 Berkley Circle				

## **E. Report Completeness Checklist**

- ☐ Inspection Summary D (System Failure Criteria Applicable to All Systems) completed
- System Information Estimated depth to high groundwater
- Sketch of Sewage Disposal System either drawn on page 15 or attached in separate file