WOOD DESTROYING PESTS INSPECTION REPORT

N<u>0</u> 649351

C	The second secon	1-00	71
Firm (PCO) Carson Valley Address P.U. Bort 2306 Gga	FXT.	License NoSSIL. Inspec	tion Date 5 - 6 - 200 S
Address P.U. Bat 2306 Gad	enerville M	189410 HA/VA/Escrow or Mortgage 1	No
Address of Property Inspected 2423	Hunterno	od Chysonlity	Zip Code
Inspection Ordered by Thomas	Varder Lag	h - Coldwell Banker	Zip Code
Inspection Report Sent to 54m			
of noted structures which were readily accessibl No inspection was made in inaccessible an object, including but not limited to moldings, flo	e VISIBLE evidence of the p c and visible. Inspection has reas which might require b or coverings, siding, ceiling GE REPORT, neither is it a antee against future infestat	reaking into, breaking apart, dismantling, re s, floors, furniture, appliances, and/or person WARRANTY as to the absence of wood-de- ions, but is indicative of the condition of the p	nade only in those areas are most likely to occur. emoval or moving of an al possessions. droying organisms. The remises ON THE DATE
A This is not a structural damage report. A This is not a guarantee against future infestations.			
This is not a structural soundness report. (Structural soundness should be determined by a qualified building expert.)			
Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company for which I am acting is financially associated in any way with or related to any party to this transaction.			
Paul Ornellas	SS40 Hispector Licens	e No.	spector
INFESTATION: (See diagram and explanation b Eviden		CONDITIONS CONDUCIVE TO INFES	STATION:
No	Yes Active Inactive	Earth-Wood Contacts	Yes No
Termites 🔀		Faulty Grades	
Other Wood-destroying Insects Wood-destroying Fungi		Insufficient Ventilation	1
, , ,		Excessive Moisture Cellulose Debris	
Location of Tag: Under Sink Crawl Space	e 🗆 Other:	(See back for definition of infestation and conditi	
		GRAPH EXPLANATIONS:	
W	W	* Exlessive Maist ab 346 Floor in Li Fron, Supphy Line Hom, Garage Sink Warder in Evan From Leak and	Space Shun Mett
		Please reference items 1.7, 5.2(1), and 5.5(1) of Home	
		Inspection Report and Exhibit: Seller Repair Itemization	
		Received and Reviewed	
Scale (optional)		by:	
Treatment Date		1,111,1	
Product Used		A Registration No.	
I have received the original or a legible copy		Signature	Date: