

REPAIR LOG

ADDRESSES REPAIRS MADE TO DEFECTS DISCOVERED THROUGH HOME INSPECTION REPORT. PLEASE CROSS-REFERENCE HOME INSPECTION REPORT



5.4(2)--SELLER SERVICED MASTER BATH WAX RING




4.5(2)--SELLER SERVICED WITH WIRE NUT TO SECURE LOOSE WIRES



2.3--SELLER SERVICED RUBBER BOOTS OF PLUMBING VENT PIPES ON ROOF



4.5(3)--SELLER SERVICED BY REPLACING FIRE ALARM



5.1(4)--SELLER SERVICED BY INSTALLING HANDLE AT SHUT-OFF VALVE



5.4--SELLER SERVICED BY SECURING LAUNDRY ROOM SINK



5.1(2)--SELLER SERVICED LEAK ON KITCHEN SINK HOT WATER



5.1(3)--SELLER SERVICED WITH EXTENDED HOT WATER LINE



5.0(1)--SELLER SERVICED SOUTH EXTERIOR HOSE BIB



10.2--SELLER SERVICED FURNACE WATER LEAK