

WOOD DESTROYING PESTS INSPECTION REPORT

NO 620891

Firm (PCO)..... License No..... Inspection Date
 Address FHA/VA/Escrow or Mortgage No
 Address of Property Inspected..... City Zip Code
 Inspection Ordered by.....
 Inspection Report Sent to.....
 Owner's Name and Address.....

This inspection was made only to determine **VISIBLE** evidence of the presence or absence of noted organisms. It is made only in those areas of noted structures which were readily accessible and visible. Inspection has been made in the areas in which infestations are most likely to occur.

No inspection was made in inaccessible areas which might require breaking into, breaking apart, dismantling, removal or moving of an object, including but not limited to moldings, floor coverings, siding, ceilings, floors, furniture, appliances, and/or personal possessions.

THIS IS NOT A STRUCTURAL DAMAGE REPORT, neither is it a WARRANTY as to the absence of wood-destroying organisms. The report is not to be construed to constitute a guarantee against future infestations, but is indicative of the condition of the premises ON THE DATE OF THE INSPECTION. This report is NOT intended to determine the presence of organisms which may be detrimental to human health.

- This is not a structural damage report. This is not a guarantee against future infestations.
- This is not a structural soundness report. (Structural soundness should be determined by a qualified building expert.)

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company for which I am acting is financially associated in any way with or related to any party to this transaction.

..... Type or Print Name of Inspector Inspector License No. Signature of Inspector

INFESTATION: (See diagram and explanation below.)

CONDITIONS CONDUCTIVE TO INFESTATION:

	Evidence of		Active	Inactive
	No	Yes		
Termites	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Other Wood-destroying Insects	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wood-destroying Fungi	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

	Yes	No
Earth-Wood Contacts	<input type="checkbox"/>	<input type="checkbox"/>
Faulty Grades	<input type="checkbox"/>	<input type="checkbox"/>
Insufficient Ventilation	<input type="checkbox"/>	<input type="checkbox"/>
Excessive Moisture	<input type="checkbox"/>	<input type="checkbox"/>
Cellulose Debris	<input type="checkbox"/>	<input type="checkbox"/>

(See back for definition of infestation and conditions conducive to infestation)

Location of Tag: Under Sink Crawl Space Other: _____

GRAPH EXPLANATIONS:



.....

Scale..... (optional)
 Treatment Date Area Treated
 Product Used..... EPA Registration No.

I have received the original or a legible copy of this form.

Received and Reviewed by: _____

Signature of Purchaser
Signature _____

Date: _____ Date

Signature _____

Date: _____

NAC 555.2577

“**Wood-destroying fungi**” means fungi that infest and destroy cellulose as that infestation and destruction relates to structural damage. The term does not include:

1. A mold located only on the surface of a structure; or
2. A mold that only causes a human health concern.

NAC 555.258

“**Wood-destroying pest**” means a pest, including, without limitation, a fungus or termite or another insect which infests and destroys cellulose as that infestation and destruction relates to structural damage. The term does not include such a pest which infests and destroys cellulose as that infestation and destruction relates to an adverse effect only on human health or other human health concerns.

NAC 555.430(3)(j)

- (1) “**Active infestation**” means the presence of living wood-destroying pests.
- (2) “**Inactive infestation**” means evidence of infestation by wood-destroying pests, without the presence of such pests

NAC 555.430(3)(k)

(1) “**Contact of wood with the earth**” means any support or other structure of cellulose that is less than 3 inches above the soil level and in contact with the inspected structure, whether it is internal or external in relation to that structure. The term does not include:

(I) A paling of a fence which is made of wood and which is less than 3 inches above the soil level and in contact with the inspected structure through otherwise acceptable structural elements.

(II) Lattice which is made of wood and which is less than 3 inches above the soil level if the lattice is physically attached to the inspected structure.

(III) An attachment to the inspected structure which is made of wood or cellulose and which is less than 3 inches above the soil level if the attachment is separated from the inspected structure by a flashing which is made of metal.

(IV) A deck which is made of wood and which is less than 3 inches above the soil and in contact with the inspected structure if the deck is separated from the inspected structure by a flashing which is made of metal and the report includes a statement indicating that the deck was excluded from the inspection or application.

(V) Skirting which is installed on a manufactured home and which is less than 3 inches above the soil and in contact with the inspected structure if the skirting is designed by the manufacturer for contact with the ground, is separated from the inspected structure by a flashing which is made of metal or is supported 3 inches or more above the soil level by pressure-treated wood.

(2) “**Faulty grade**” means a condition in which:

(I) A floor joist or stringer is less than 12 inches above the soil level;

(II) The top of the foundation is less than 3 inches above the adjacent soil level; or

(III) The drainage is such that there is visible evidence of exposure of surface water on the structure.

(3) “**Insufficient ventilation**” means less than 1 square foot of ventilation per 300 square feet of crawl space, less than 1 square foot for every 1500 square feet of ground area covered by a vapor barrier and less than four areas permitting ventilation. The term “insufficient ventilation” does not include a crawl space which is:

(I) Mechanically ventilated; and

(II) Free of wood-destroying fungi and excessive moisture.

(4) “**Excessive moisture**” means actual moisture on the wood or wood products used in the structure.

(5) “**Cellulose debris**” means any such debris that is of a size that can be raked and in the aggregate comprises one-half cubic foot or more, or a stump or any other wood that is imbedded in a footing and constitutes a contact of wood with the earth. The term does not include pressure-treated wood that is used to support a manufactured home or the skirting of a manufactured home.

7. As used in this section, “pressure-treated wood” means wood or wood products that:

(a) Are pressure-treated or certified by the Board of Review of the American Lumber Standard Committee, Inc.;

(b) Are designed by the manufacturer for contact with the ground;

(c) Are guaranteed against structural damage by termites or fungal decay; or

(d) Are described in paragraph (a), (b) or (c) and have surfaces which have been cut, if those surfaces have been treated with a preservative for wood and the wood or wood products have been inspected and determined to be free of infestation.

More information on Nevada’s wood-destroying pest inspection reports and reporting regulations can be found on the web at <http://www.leg.state.nv.us/NAC/NAC-555.html#NAC555Sec250>.

Wood Destroying Insect Inspection Report Notice: Please read important consumer information on page 2.

Section I. General Information Inspection Company, Address & Phone	Company's Business Lic. No.	Date of Inspection
	Address of Property Inspected	
Inspector's Name, Signature & Certification, Registration, or Lic. #	Structure(s) Inspected	



Section II. Inspection Findings This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. **Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:**

- A. No visible** evidence of wood destroying insects was observed.
- B. Visible** evidence of wood destroying insects was observed as follows:
 - 1. Live insects (description and location): _____
 - 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location): _____
 - 3. **Visible** damage from wood destroying insects was noted as follows (description and location): _____

NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.

Yes No It appears that the structure(s) or a portion thereof may have been previously treated. Visible evidence of possible previous treatment:

The inspecting company can give no assurances with regard to work done by other companies. The company that performed the treatment should be contacted for information on treatment and any warranty or service agreement which may be in place.

Section III. Recommendations

No treatment recommended: (Explain if Box B in Section II is checked) _____

Recommend treatment for the control of: _____

Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed or inaccessible:	The inspector may write out obstructions or use the following optional key:
<input type="checkbox"/> Basement _____ <input type="checkbox"/> Crawlspace _____ <input type="checkbox"/> Main Level _____ <input type="checkbox"/> Attic _____ <input type="checkbox"/> Garage _____ <input type="checkbox"/> Exterior _____ <input type="checkbox"/> Porch _____ <input type="checkbox"/> Addition _____ <input type="checkbox"/> Other _____	1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabinets or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow 21. Unsafe conditions 22. Rigid foam board 23. Synthetic stucco 24. Duct work, plumbing, and/or wiring

Section V. Additional Comments and Attachments (these are an integral part of the report)

Attachments _____

Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage, repair, and treatment history has been disclosed to the buyer.	Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.
X	X

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection:** A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. ***For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms.*** **This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.**
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites:** FHA and VA require treatment when any active infestation of subterranean termites is found. If signs of subterranean termites — but no activity — are found in a structure that shows no evidence of having been treated for subterranean termites in the past, then a treatment should be recommended. A treatment may also be recommended for a previously treated structure showing evidence of subterranean termites — but no activity — if there is no documentation of a liquid treatment by a licensed pest control company within the previous five years unless the structure is presently under warranty or covered by a service agreement with a licensed pest control company.
- 3. Obstructions and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects.** Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- 5. Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.**