## WOOD DESTROYING PESTS INSPECTION REPORT

No 642772

	,	_		1100	1. 00 -
Firm (PCO). Carsus 4 Address P.O. Box 2306	alle	y EXT.	Licens	e No. 55.79 Insp	ection Date 10-28-2
Address 4.0. Box 2306	Gyno	inexpille NV	894/0 FHA/	A/Escrow or Mortgage	No
Address of Property Inspected . L.	21/	ceetly pr.		Dayten	24403 Zip Code
Inspection Ordered byT. by	105 V	anne Laar	- Loldmer	1Backer	
Inspection Report Sent to	ne				
Owner's Name and Address. This inspection was made only to	determin				is made only in those areas
of noted structures which were readil No inspection was made in inac object, including but not limited to m THIS IS NOT A STRUCTURA report is not to be construed to constit OF THE INSPECTION. This report	y accessib cessible a oldings, flo L DAMAC tute a guar	le and visible. Inspection reas which might requir oor coverings, siding, cei GE REPORT, neither is rantee against future infe	has been made in the re breaking into, break lings, floors, furniture, it a WARRANTY as estations, but is indicate	areas in which infestation king apart, dismantling, appliances, and/or person to the absence of wood-of ive of the condition of the	ns are most likely to occur, removal or moving of an onal possessions. destroying organisms. The e premises ON THE DATE
This is not a structural damage rep	port.	This is not a guarante	e against future infest		
This is not a structural soundness		This is not a mold instructural soundness sl		by a qualified building	expert.)
Neither I nor the company for wh	nich I am a	cting have had, presently	have, or contemplate l	naving any interest in the	property. I do further state
that neither I nor the company for wh	ich I am a	cting is financially assoc	iated in any way with	or related to any party to	this transaction.
Parl Ornallas		6500	a Pin	u Cham	
Type or Print Name of Inspe			icense No.	Signature of	f Inspector
INFESTATION: (See diagram and exp	planation t Evider			S CONDUCIVE TO INF	
	No	Yes	Earth-Wood Co	ontacts	Yes No
Termites	28				
Other Wood-destroying Insects	×		Insufficient Ve	ntilation	The state of the s
Wood-destroying Fungi	×		Excessive Moi	sture	
Location of Tag: Under Sink C	Crawl Spac	ce Other:		risdefinition of infestation and cond	
	TIII		,		
			GRAPH EXP	LANATIONS:	
			All	Clear	
			TO DESCRIPTION OF THE PROPERTY	-	
			and married source	N.	
	nemilje se si se samber se si su		THE DESCRIPTION OF THE PROPERTY OF THE PROPERT		
Scale(optional)	and and and and	and the second control of the second control	ne and occupantion are made		
Trestment Date		Area Treated			
Product Used			EPA Registration No.		
I have received the original or a le					
	Signature	of Purchaser			Date