

505502

# ESTIMATE OF REPAIRS

©2001 RECIFORM® 41429

OWNER: [REDACTED]				DATE: 5-20-21
ADDRESS: 857 LYELL WAY, GARDNERVILLE,		PHONE:		EST. NO.
INSURANCE CO.				ORDER NO.
ADDRESS:		PHONE:		LICENSE NO.
YEAR MAKE:	MODEL:	COLOR:	TYPE:	SERIAL NO.

QUANTITY	DESCRIPTION OF LABOR OR MATERIAL	PART NO.	MATERIAL	LABOR
1	SERVICE CALL @ 1 HR.			65
	INSTALL 6-FIRE/SMOKE DETECTORS-NON WIRED		0	0



LOWE'S HOME CENTERS, LLC  
 430 FAIRVIEW DRIVE  
 CARSON CITY, NV 89701 (775) 881-2460

SALES: FSTLANE4 13 TRANS: 14452592 05-19-21

986240 FA 10YR BATTERY PHOTO SHD 131.88  
 6 @ 21.98  
 661845 RAYOVAC FUSION 9V 2-PACK 25.44  
 3 @ 8.48

SUBTOTAL: 157.32  
 TAX: 11.96  
 INVOICE TOTAL: 169.28  
 DEBIT: 169.28

AMOUNT: 169.28 AUTHCD: 043034  
 CHIP REFID: 102400016218 05/19/21 12:29:08

#PIN Verified  
 TRACE: 00922060  
 PURCHASE CASH BACK TOTAL DEBIT  
 169.28 0.00 169.28  
 APL: US DEBIT TVR: 8080048000  
 AID: A000000980840 TSI: 6800  
 STORE: 1024 TERMINAL: 06 05/19/21 12:29:52  
 # OF ITEMS PURCHASED: 9  
 EXCLUDES FEES, SERVICES AND SPECIAL ORDER ITEMS



THANK YOU FOR SHOPPING LOWE'S.

PARTS PRICES BASED ON STANDARD CATALOG PROCUREMENT. PARTS PRICES ARE SUBJECT TO CHANGE WITHOUT NOTICE. PROCUREMENT AND DELIVERY CHARGES MAY BE ADDED FOR SPECIAL SERVICE ON ITEMS NOT AVAILABLE LOCALLY.		TOTAL MATERIAL	
OLD PARTS REMOVED FROM CARS WILL BE JUNKED UNLESS OTHERWISE INSTRUCTED IN WRITING.		TOTAL LABOR	1
THE ABOVE IS AN ESTIMATE BASED ON OUR INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER WORK HAS BEEN OPENED UP. OCCASIONALLY AFTER WORK HAS BEEN STARTED, WORN PARTS ARE DISCOVERED WHICH ARE NOT EVIDENT ON FIRST INSPECTION. BECAUSE OF THIS ABOVE PRICES ARE NOT GUARANTEED.		TOTAL MATERIAL	
ESTIMATED BY:	ESTIMATE APPROVED BY:	TAX	1
AUTHORIZED AND ACCEPTED		PAID OUT-TOW & STORAGE	
BY OWNER OR AGENT		SUBLET REPAIRS	
DATE:		TOTAL	65 00