



PERMIT


On-Site Wastewater Treatment System Inspection Report
Public Health – Division of Health Protection
406.256.2770

County Tracking Request #: 17499 EHS Permit #: 17358

Address: 2907 Clarks Point Dr. Legal Description: Clarks Fork River Ranch 2nd L17

System Type: Standard Chamber Total Area Installed: 336 x 2 = 672 ft²

Additional System Details: cistern/water storage tank filled by shared wells (per COSA)
>10 ft to west PL




Date: 7/7/21 Septic Installer: clear creek Sanitarian: elam hanni

Note: Inspection report denotes compliance with plans submitted by the applicant and to the Yellowstone City-County Health Department Rules and Regulations (Rule #3). It does not guarantee performance or longevity of system. (Revised 11/2018)

Please send perm. + here

Builder: Ventling Building & Development Inc

2070 Ranch trail Rd,
Laurel, Mt. 59044



Lot 17
3.99 acres

House Specs:

Location:
Lot 17 Clarks Point Sub
2907 Clarks Point Dr.
Laurel, mt,

Specs:
2 - bedroom rancher
w/ 2 bedroom finished
basement
(4) total

Water:
well from river feeds
cistern
Excavator:

Clear Creek Const.

Phil Ventling

Clarks Point Rd.